


BOWMAR CONSUMER PRODUCTS DIVISION 531 Main Street, Acton, Mass. 01720, Tel: (617) 486-3192

MX80 Electronic Calculator

Instructions For Use



INTRODUCTION


Your Bowmar MX80 Calculator represents a significant engineering achievement resulting in full-size capability in a pocket-size package. Advances in miniaturized computer circuits using single-chip LSI (Large Scale Integration), LED (Light Emitting Diode) display technology, and a unique snap-action keyboard have provided a rugged, reliable unit, and the selfcontained nickel-cadmium rechargeable batteries permit convenient use even when AC power is not available.

The MX80 performs addition, subtraction, multiplication, division and percentage including chain or mixed multiplication and division, and utilization of a stored constant. It also has a capability to mark up or discount a number after the percentage is calculated. Ten digits are provided for entry and readout with a full floating decimal and a positive or negative sign. Additional display indicators denote Power On, Low Battery, Overflow, Error and Minus Sign. A "Battery Saver" feature to extend battery operating time causes the display to blank out approximately 30 seconds after the last entry, without the loss of a problem.

It is suggested that the following instructions be read with the calculator at hand, and that all examples be performed with the unit to increase your familiarity. A short outline of operating procedures is also printed on the back of the calculator.

OPERATION

- AC Operation:
 - Set the switch on the back of the Charger/ Power Supply to the electrical outlet voltage, i.e., 115 or 230 Volts. Plug the Charger into the outlet and the connector into the Calculator. (Note that the connector is keyed.) After these connections, the power switch may be turned on and operation started.
- Battery Operation:
 - Disconnect the Charger cord and turn the power switch "ON". With normal use a full battery charge can be expected to supply about 5 hours of working time. NOTE: When the low battery indicator (L) on the display is lighted, do not continue battery operation. This indicates need for a battery charge. Use of the Calculator can be continued during the charge cycle. Charging will continue whether calculator is on or off.
- Battery Charging:
 - Simply follow the same procedure as in AC operation. The Calculator may be used during the charge period if desired. In order to fully charge a battery which has been completely discharged, 7 hours is required. In most cases, an overnight charge should be adequate.
- NOTE: Although no damage will result from prolonged periods with the Charger connected, it is advisable to remove the Charger when it is not in use or after a full recharge cycle. CAUTION: To avoid possible damage, use only the charger provided with the calculator.



Turns Calculator "ON" &

Slide switch with 2 positions; in the up position, the 'K' operation is in effect. Use of 'K' allows a number to be entered and retained as a "constant" for series multiplication or division.

Performs %, mark-up, and discount operation.

Clears the Calculator and the display of all numbers.

Clears the display of the previous keyboard entry.

Enters a "multiply"

Enters a "divide" command.

Adds the entered number, or carries out a previously entered "multiply" or "divide" command.

Adds a minus sign to an entry, Subtracts the entered number or completes a previously entered "multiply" or "divide" command.

PRELIMINARY INSTRUCTIONS

- 1. To clear (erase)
 - A. Touch the C key
 - B. Cleared display will be:

2. To enter (write a number)

Example: enter 123.45

- A. First, clear by touching c
- B. Then touch number and decimal keys for 123.45 one at a time. Always start with the left hand digit and progress from left to right. Display will then be:

3. To clear an incorrect entry

Example: 48+ 12 is your calculation

- A. You have already entered 48 Display is:
- B. You now touch the reakey Display will be:

- C. Then you enter 13 by mistake The display is:
- D. To clear 13, touch the CE key Display will be:
- E. Then enter '12' Display will be:

0.

123.45


48.

48.

÷

Display will be:

Note: Use CE during, or immediately after entry of a number.



CALCULATIONS

1. ADDITION


Example #1: To calculate 16.39 + 9.83 =Do these steps display will be

а.	Touch C		0.
b.	Enter 16.39		16.39
c.	Touch +=		16.39
d.	Enter 9.83		9.83
e.	Touch +=	Answer	26.22

Example #2: To calculate 16 + 9 + 8.3 + 4.1 =

Do these steps	display will be	
a. Touch	0.	
b. Enter 16	16.	
c. Touch +=	16.	
d. Enter 9	9.	
e.Touch 🕶	25.	
f. Enter 8.3	8.3	
g. Touch 🕶	33.3	

Answer



i. Touch +=

0. 39

4.1

37.4

c. Touch += d. Enter 3.6 ¢

e

e. Touch -=

Do these steps

a. Touch c

b. Enter 12.81

Answer

Example #2: To calculate 23 - 6 + 2.1 - 5 =Do these steps

- a. Touch c
- b. Enter 23
- c. Touch +=
- d. Enter 6
- e.Touch 🛶
- f. Enter 2.1
- g. Touch +≠
- h. Enter 5


••

i. Touch ==


Answer


2. SUBTRACTION


Example #1: To calculate 12.81 - 3.6 = display will be




display will be








Ļ



4. DIVISION


-

Example #1: To calculate $376 \div 53 =$ Do these steps display will be




Example #2: To calculate $81 \div 3 \div 9 =$ Do these steps display will be







.





Example #3: 10% discount, 5% sales tax on an item of \$250.






.





7. EXPONENTS



i. Push 'K' off (down)

8. OVERFLOW INTERPRETATION

The positive or negative overflow indicator indicated by \square or \square respectively, will appear when the display capacity of the calculator is exceeded.

For example, multiplication of two positive numbers 12345678×345678 will give the following display

or multiplication of a positive and a negative number

12345678 🚿 --- 345678

will give the following display

The "" " or "" " symbol indicates positive or negative "overflow" respectively, and indicates an answer of more than 10 digits shown. To obtain the correct decimal location for either case, simply record the displayed number and move the decimal point 10 places to the right. The real answer will then be:

> $\pm 4.267,629,279,000.$ 🗋 10 places 🗈

This procedure applies to all operations; multiplication, division, addition, subtraction and percentage. Use the 'C' key to clear the overflow.

9. TO RECALL THE DISPLAY AFTER 'BLANKING'

During battery operation, the display will automatically turn off, if there is no keyboard activity for about 30 seconds. This feature is provided to conserve the battery power. Depress any key on the keyboard to recall the 'blanked' display.

426:7629279

426.7629279

BATTERY NOTES

- 1. With normal use at room temperature, a full battery charge can be expected to supply about 5 hours of accumulated working time.
- 2. The Calculator may be used while its battery is charging.
- 3. Batteries that have been neither used nor charged for as long as 2 or 3 months will suffer substantial loss of operating time through a tendency to self-discharge. As a general rule, batteries lose about 1% charge per day due to self-discharge, at normal temperatures.
- 4. For optimum performance and long life:
 - a. Alternate frequently between Battery and AC power.
 - b. Operate at or near normal room temperatures.
 - c. Charge as soon as possible upon appearance. of the Low-Battery indicator.
- 5. Recharge time is 7 hours for a fully discharged battery.
- 6. The Low-Battery indicator is designed to appear as soon as battery voltage drops to the lowest value that will support optimum performance of the Calculator. Should further discharge occur, through continued operations or self-discharge, the Low-Battery indicator may fail to appear. Do not continue to operate on batteries when this condition is noted, or a damaged battery may result.
- 7. As a general rule, if improper operation occurs, first try the Calculator with its charger connected. If operation is then normal, this indicates the batteries are low.
- Do not store the unit in high temperature areas. such as the top of radiators or the rear deck of automobiles exposed to the sun. The Calculator will operate satisfactorily over an ambient temperature range of 0 to 50C (32 to 122F) and relative numidity to 95%.

WARBANTY

Bowmar/ALI, Inc. warrants to the purchaser of this new Bowmar Calculator that if the machine or any part thereof in the judgment of Bowmar is proven to be defective in material or workmanship within one year from date of original purchase, such defects will be repaired or replaced (at the Company's option) free of charge for parts and labor.

This warranty does not apply to any product which has been damaged by accident or which has been misused, abused, altered, or repaired by anyone other than Bowmar.

This warranty is in lieu of all other warranties. expressed or implied, and no person is authorized to assume for Bowmar any other liability in connection with the sale of this product.

To obtain repairs, the Calculator should be delivered, prepaid, to Bowmar/ALI. Inc. at address shown below. In-warranty units will be returned postage prepaid.

BOWMAR/ALI, INC., ACTON, MASS. 01720

A901-087-0